



LVR-50 PQ Pilot Program


Power Quality issues on a rural feeder

- A lumber and truss operation was causing Flicker, Sags, & Swells on the circuit primary
- Residential customer (who is a commercial electrician) persistently complained to the PUC
 - ➤ High voltage was shutting down PV inverters
 - Flicker & deep Sags tripping off appliances





PGE LVR 420002_8/6/20



Blue line is input --- Red line is output